


To existing Annex -
See attached sheet



Club House Main Building
First Floor

Robert D. Pike
21 Andover St,
Ludlow, Vermont

